




Table rock Dam service bridge over dam



Gate lifting equipment coated with P-38 modified



Motor



Bull gear



Not all structural steel under deck was topcoated



All structural steel under equipment was topcoated